

id 6024

## Binnenvaartschip

[50,8 m kraanschip](#)

Schip-ID	6024
Categorie	<a href="#">Binnenvaartschip</a>
bouwjaar	2020
Prijs	\$3,200,000
Verzenddatum toegevoegd	2022-05-30
Toegevoegd door	<a href="#">Vlad (Varamar)</a>

## Afmetingen van het schip

Lengte over alles (LOA), m	50.8
Diepte, m	3.6
Diepgang van het schip, m	1.414

## Extra informatie

Hoofd motor	1000hp + 1000hp
Zelfrijdend	

Vergelijkbare schepen	<a href="#">Toon vergelijkbare schepen</a>
Verzoeken	<a href="#">Aankoopverzoeken overeenkomend</a>
e-mail	<a href="#">E-mail verzenden</a>



FQ5008 吊机的500吨是定期维护的，保养是定期加注润滑油可以，润滑系统每个月加一次，其余地方半年加一次。

The FQ5008 crane (SPT) is easy to maintain. Maintenance is the need to fill lubricating oil all can be regularly, showing bearing filling once a month, the rest of the 6 months filling once.

其余部分在定期保养的，配件需要备一些备用零件，液压油选择，然后电液的一些接触器点什么的，坏了就换，不用在定期更换的，吊机坏了，人员可以外派维修。

主要易损件如下。（根据使用状况为2到3年配件用量）

There is no need to maintain the rest, spare parts need to prepare part of the brake pad, hydraulic actuator, and then some electrical contact contacts, broken to replace, there is no regular replacement, if the crane has problem which cannot be fixed, personnel can be dispatched to repair.

The main wearing parts are as follows (2 to 3 years of spare parts consumption according to the use)

名称	数量	单价	总价
LC1-F225A 4P接触器	1	3702	3702
LC1-F225A 4P线圈	1	570	570
LC1-F225A 4P主触点	1	1450	1450
LC1-D09接触器	2	55	110
KXM2LBP7中阻	40	20	800
LC1-D820MTC接触器	1	7870	7870
3RT3075 400A接触器	1	2570	2570
3RT3075 400A线圈	1	350	350
3RT3075 400A主触点	1	1124	1124
主付机刹车油泵	2	2780	5560
主付机刹车片	16	300	4800
变幅方向节	1	2200	2200
主付机吊钩	2	160	320
转向刹车皮	8	165	1320
总价			33076

以上价格为人民币价格，总计 33076 元（美元的 5250 美金），（根据使用状况为2到3年配件用量） The above price is RMB 33,076 yuan (or 5,250) in total. (2 to 3 years of spare parts consumption depending on usage)

